



ΑΠΑΡΑΙΤΗΤΗ Η ΣΤΗΡΙΞΗ ΣΤΟΝ ΤΟΙΧΟ







2 ΧΡΟΝΙΑ ΕΓΓΥΗΣΗ


|   |             |     |
|---|-------------|-----|
| A | 2x 638x430  | 2/3 |
| B | 638x426     | 2/3 |
| C | 665x426     | 2/3 |
| D | 1599x430    | 1/3 |
| E | 1599x430    | 1/3 |
| F | 455x386     | 1/3 |
| G | 2x 542x386  | 1/3 |
| H | 2x 329x1587 | 1/3 |
| I | 2x 348x80   | 3/3 |
| J | 2x 1400x80  | 1/3 |
| K | 632x449     | 2/3 |
| L | 2x 632x619  | 3/3 |














|                  |                 |                 |                  |                  |                 |                 |                 |
|------------------|-----------------|-----------------|------------------|------------------|-----------------|-----------------|-----------------|
| 28x<br><br>10174 | 4x<br><br>10072 | 4x<br><br>10215 | 28x<br><br>10013 | 40x<br><br>50317 | 6x<br><br>40149 | 3x<br><br>40114 | 6x<br><br>50738 |
| 2x<br><br>51066  | 2x<br><br>10060 | 2x<br><br>10021 | 28x<br><br>10001 | <br>10033        |                 |                 |                 |





1.1








1.2



1.3



1.4



1.5

