









**ΟΔΗΓΙΕΣ ΣΥΝΑΡΜΟΛΟΓΗΣΗΣ**  
**ASSEMBLY INSTRUCTIONS**  
**Инструкция за сглобяване**









<b>A</b> <input type="checkbox"/>  <b>Ax4</b>	<b>B</b> <input type="checkbox"/>  <b>M15x12mm</b> <b>Bx4</b>	<b>C</b> <input type="checkbox"/>  <b>M12x10mm</b> <b>Cx4</b>
--	---	---

<b>D</b> <input type="checkbox"/>  <b>M7x39mm</b> <b>Dx8</b>	<b>E</b> <input type="checkbox"/>  <b>M8x30mm</b> <b>Ex8</b>	<b>F</b> <input type="checkbox"/>  <b>M6x30mm</b> <b>Fx8</b>
--	--	--


<b>G</b> <input type="checkbox"/>  <b>Gx2</b>	<b>H</b> <input type="checkbox"/>  <b>M34x360mm</b> <b>Hx4</b>	<b>I</b> <input type="checkbox"/>  <b>M67x70mm</b> <b>Ix4</b>	<b>J</b> <input type="checkbox"/>  <b>M4x10mm</b> <b>Jx4</b>	<b>K</b> <input type="checkbox"/>  <b>M4x12mm</b> <b>Kx20</b>
--	--	---	--	---

<b>L</b> <input type="checkbox"/>  <b>M3.5x14mm</b> <b>Lx12</b>	<b>M</b> <input type="checkbox"/>  <b>M5x40mm</b> <b>Mx8</b>	<b>N</b> <input type="checkbox"/>  <b>M4x19mm</b> <b>Nx2</b>	<b>O</b> <input type="checkbox"/>  <b>Ox4</b>	<input type="checkbox"/>
---	--	--	---	--------------------------


1




1A




1B




2




3




4




5







6



7





8




**x 2**

9A




**x 2**

9



**x 2**


10



**x 2**



11



12

