








A		M6x20mm	X16
B		5mm	X1
C			X1

D		X 2
E		X 2



Please don't over-tighten all screws before adjusting balance of the whole chair.
 Παρακαλώ μην βιδώσετε πολύ σφιχτά τις βίδες πριν ισορροπήσετε την καρέκλα.
 Моля, не затягвайте прекалено много винтове, преди да регулирате баланса на стола

Tight all the screws to 100%
 Σφίξτε τις βίδες στο 100%
 Затегнете всички винтове до