




A	x14	B	x8	C	x22	D	x22	E	x8	F	x6
						4x40mm					
G	x2	H	x18	I	x2	J	x6	K	x3	L	x3
		3x12mm									
M	x6	N	x12	O	x10	P	x6				
		6x12mm		4x14mm							




1




a.1



a.2




a.3




F	x2	H	x6
			
			3x12mm





2




180°



180°



3




A	x8
	


a.1



a.2




a.3




F	x4	H	x12
			
			3x12mm

4




C	x16
	

5




B	x8	E	x8
			

6




7




D	x8
	
4x40mm	

8




N	x12	O	x8
			
6x12mm		4x14mm	

9



P	x6
	
	


10



A	x6	M	x6	C	x6	D	x12	K	x3	L	x3
											
						4x40mm					

x3


11



J x2




12



J x2




13



J x2



14



D x2 I x2 O x2 G x2

