


2 ΧΡΟΝΙΑ ΕΓΓΥΗΣΗ









A	2x 373x400	1/1
B	373x320	1/1
C	2x 1200x400	1/1
D	393x1188	1/1
E	425x1197	1/1


12x 10174	12x Φ 8x30 10013	12x 50317	3x 40161	2x 50948	6x 50449	2x 51066
2x 10060	2x Φ 6/80 10021	12x Φ 4/35 10019	27x Φ 3,5/16 10001	 10033		

1




1.1














1.2










1.3




1.4





2 ΧΡΟΝΙΑ ΕΓΓΥΗΣΗ



A	2x 568x400	1/1
B	2x 600x400	1/1
C	568x380	1/1
D	588x588	1/1
E	597x597	1/1

8x 10174	8x Φ 8x30 10013	8x 50317	2x 40121	1x 40114	4x 50332	2x 51066
2x 10060	2x Φ 6/80 10021	16x Φ 3,5/16 10001	 10033			

